

Exlaser is not functioning, returning <no card detected> when running.

- Start > settings > control pannel > add or remove programs
- remove <Advantech DAQNav products>
- right click on <My computer> > properties > Hardware > device manager > scan for new hardware and install PCI1711 driver
- Use ExlaserLT to replace gas cylinder
- on desktop install < DAQNav PCI1711_3.2.11.0.exe> select modify mode
- Use LaserGUI for production.