




Setup - UpsMonitor

Installing
Please wait while Setup installs UpsMonitor on your computer.


Extracting files...
C:\Program Files\Bis\UpsMonitor_v1.0.0.1\UpsMonitor.exe

















The software you are installing for this hardware:
American Power Conversion USB UPS (Apcupsd)

has not passed Windows Logo testing to verify its compatibility with Windows XP. (Tell me why this testing is important.)

Continuing your installation of this software may impair or destabilize the correct operation of your system either immediately or in the future. Microsoft strongly recommends that you stop this installation now and contact the hardware vendor for software that has passed Windows Logo testing.

